

Indx	Title V	EII	Intelatrac	O/T Request	Alarm Actions		
OPS Monitor	21 Day Plan	Maximo	Trap	Corrective Action	Exapilot	Refined Orders	Find

Today Date:	8/5/2012	Name:	ca	Submit Email	<i>Report problems. Send in suggestions, improvements, changes, ideas.</i>
Shift:	Days	Crew:	A		
<input checked="" type="radio"/> Yes <input type="radio"/> No		Are you in compliance with all CBT & Refresher Training?		Radio #	

Safety

MP-1165 SUCTION MOV CIRCUIT BOARD BYPASSED-REFER TO PSM DATABASE "BYPASS SAFETY DEVICE DOCUMENT" #340 MP-1165 & TP-1165 EBV'S BOTH IN BAD ORDER

Environmental

OMC Communications / Maintenance Plan Crude PCO

4 Crude

4 Crude Information

Crude switch 07→04
2 cut→DHT rate hydraulically limited by DHT

4 Crude Instrumentation Notes

11HCV-605 (60 PASS 5) STICKING
11TI596 READING B/O 359997
K-1100A LO LUBE ALARM 360993
E-1186-1 B/O

Long Term Issues

Feed Tanks				
PUMP #	Tank #	Crude Type	Gravity	FD Rate
P4700	3104	Arab	34.6/.01/.01	190
P4701	3103	ANS	33.2/0/.80	60
P4702				

☒ On
 ☐ Off

ATMOS. DMC

If Off, Why:

☒ On
 ☐ Off

VAC. DMC

If Off, Why:

☒ On
 ☐ Off

STAB. DMC

If Off, Why:

☒ On
 ☐ Off

F1100A DMC

If Off, Why:

☒ On
 ☐ Off

F1100B DMC

If Off, Why:

Indx	Title V	EII	Intelatrac	O/T Request	Alarm Actions		
OPS Monitor	21 Day Plan	Maximo	Trap	Corrective Action	Exapilot	Refined Orders	Find

Today Date:	8/5/2012	Name:	Herring, Steven B.	Submit Email	<i>Report problems. Send in suggestions, improvements, changes, ideas.</i>
Shift:	Nights	Crew:	C		
<input checked="" type="radio"/> Yes <input type="radio"/> No	Are you in compliance with all CBT & Refresher Training?			Radio #	

Safety

MP-1165 SUCTION MOV CIRCUIT BOARD BYPASSED-REFER TO PSM DATABASE "BYPASS SAFETY DEVICE DOCUMENT" #340
MP-1165 & TP-1165 EBVS BOTH IN BAD ORDER

Environmental

OMC Communications / Maintenance Plan Crude PCO

4 Crude

4 Crude Information

Crude switch 07→04
2 cut→DHT rate hydraulically limited by DHT

4 Crude Instrumentation Notes

11HCV-605 (60 PASS 5) STICKING
11TI596 READING B/O 359997
K-1100A LO LUBE ALARM 360993
E-1186-1 B/O

Long Term Issues

Feed Tanks				
PUMP #	Tank #	Crude Type	Gravity	FD Rate
P4700	3104	Arab	34.6/.01/.01	190
P4701	3103	ANS	33.2/0/.80	60
P4702				

☒ On
 ☐ Off

ATMOS. DMC

If Off, Why:

☒ On
 ☐ Off

VAC. DMC

If Off, Why:

☒ On
 ☐ Off

STAB. DMC

If Off, Why:

☒ On
 ☐ Off

F1100A DMC

If Off, Why:

☒ On
 ☐ Off

F1100B DMC

If Off, Why:

Indx	Title V	EII	Intelatrac	O/T Request	Alarm Actions		
OPS Monitor	21 Day Plan	Maximo	Trap	Corrective Action	Exapilot	Refined Orders	Find

Today Date:	8/6/2012	Name:	Dotson, Mike	Submit Email	<i>Report problems. Send in suggestions, improvements, changes, ideas.</i>
Shift:	Days	Crew:	B		
<input type="radio"/> Yes <input type="radio"/> No		Are you in compliance with all CBT & Refresher Training?		Radio #	

Safety
MP-1165 SUCTION MOV CIRCUIT BOARD BYPASSED-REFER TO PSM DATABASE "BYPASS SAFETY DEVICE DOCUMENT" #340
MP-1165 & TP-1165 EBV'S BOTH IN BAD ORDER

Environmental

OMC Communications / Maintenance Plan Crude PCO

4 Crude

4 Crude Information
* P-1195A, clean-up and LOTO, updating seals.
* P-1149's, leak under insulation, cutting feed, CFD on scene.
* Crude Feed, cut 10m.

--
2 cut → DHT rate hydraulically limited by DHT

4 Crude Instrumentation Notes
11HCV-605 (60 PASS 5) STICKING
11TI596 READING B/O 359997
K-1100A LO LUBE ALARM 360993
E-1186-1 B/O

	Long Term Issues
--	------------------

Feed Tanks

PUMP #	Tank #	Crude Type	Gravity	FD Rate
P4700	3104	Arab	34.6/.01/.01	190
P4701	3103	ANS	33.2/0/.80	60
P4702				

☒ On ☐ Off

ATMOS. DMCIf Off, Why:

☒ On ☐ Off

VAC. DMCIf Off, Why:

☒ On ☐ Off

STAB. DMCIf Off, Why:

☒ On ☐ Off

F1100A DMCIf Off, Why:

☒ On ☐ Off

F1100B DMCIf Off, Why:

Indx	Title V	EII	Intelatrac	O/T Request	Alarm Actions		
OPS Monitor	21 Day Plan	Maximo	Trap	Corrective Action	Exapilot	Refined Orders	Find

Today Date:	8/6/2012	Name:	Herring, Steven B.	Submit Email <i>Report problems. Send in suggestions, improvements, changes, ideas.</i>	
Shift:	Nights	Crew:	C		
<input checked="" type="radio"/> Yes <input type="radio"/> No		Are you in compliance with all CBT & Refresher Training?		Radio #	

Safety

MP-1165 SUCTION MOV CIRCUIT BOARD BYPASSED-REFER TO PSM DATABASE "BYPASS SAFETY DEVICE DOCUMENT" #340 MP-1165 & TP-1165 EBV'S BOTH IN BAD ORDER

Environmental

OMC Communications / Maintenance Plan Crude PCO

4 Crude

4 Crude Information

* P-1195A, clean-up and LOTO, updating seals.
* P-1149's, line leak Plant S/ D all pumps down, MCC power S/ D, ALL Handswitches thrown
*

4 Crude Instrumentation Notes

11HCV-605 (60 PASS 5) STICKING
11TI596 READING B/O 359997
K-1100A LO LUBE ALARM 360993
E-1186-1 B/O

Long Term Issues

Feed Tanks

PUMP #	Tank #	Crude Type	Gravity	FD Rate
P4700	3104	Arab	34.6/.01/.01	190
P4701	3103	ANS	33.2/0/.80	60
P4702				

☐ On ☐ Off

ATMOS. DMCIf Off, Why:

☐ On ☐ Off

VAC. DMCIf Off, Why:

☐ On ☐ Off

STAB. DMCIf Off, Why:

☐ On ☐ Off

F1100A DMCIf Off, Why:

☐ On ☐ Off

F1100B DMCIf Off, Why:

Indx	Title V	EII	Intelatrac	O/T Request	Alarm Actions		
OPS Monitor	21 Day Plan	Maximo	Trap	Corrective Action	Exapilot	Refined Orders	Find

Today Date:	8/7/2012	Name:	Dotson, Mike	Submit Email	<i>Report problems. Send in suggestions, improvements, changes, ideas.</i>
Shift:	Days	Crew:	B		
<input type="radio"/> Yes <input type="radio"/> No		Are you in compliance with all CBT & Refresher Training?		Radio #	

Safety

MP-1165 SUCTION MOV CIRCUIT BOARD BYPASSED-REFER TO PSM DATABASE "BYPASS SAFETY DEVICE DOCUMENT" #340 MP-1165 & TP-1165 EBVS BOTH IN BAD ORDER

Environmental

OMC Communications / Maintenance Plan Crude PCO

4 Crude

4 Crude Information

* Plant S/ D, all pumps down, MCC power S/ D, ALL Hand switches thrown.

4 Crude Instrumentation Notes

11HCV-605 (60 PASS 5) STICKING
11TI596 READING B/O 359997
K-1100A LO LUBE ALARM 360993
E-1186-1 B/O

Long Term Issues

Feed Tanks

PUMP #	Tank #	Crude Type	Gravity	FD Rate
P4700	3104	Arab	34.6/.01/.01	190
P4701	3103	ANS	33.2/0/.80	60
P4702				

☐ On ☒ Off

ATMOS. DMCIf Off, Why:

Unplanned Shutdown

☐ On ☒ Off

VAC. DMCIf Off, Why:

Unplanned Shutdown

☐ On ☒ Off

STAB. DMCIf Off, Why:

Unplanned Shutdown

☐ On ☒ Off

F1100A DMCIf Off, Why:

Unplanned Shutdown

☐ On ☒ Off

F1100B DMCIf Off, Why:

Unplanned Shutdown

Indx	Title V	EII	Intelatrac	O/T Request	Alarm Actions		
OPS Monitor	21 Day Plan	Maximo	Trap	Corrective Action	Exapilot	Refined Orders	Find

Today Date:	8/7/2012	Name:	ca	Submit Email	<i>Report problems. Send in suggestions, improvements, changes, ideas.</i>
Shift:	Nights	Crew:	A		
<input checked="" type="radio"/> Yes <input type="radio"/> No		Are you in compliance with all CBT & Refresher Training?		Radio #	

Safety
MP-1165 SUCTION MOV CIRCUIT BOARD BYPASSED-REFER TO PSM DATABASE "BYPASS SAFETY DEVICE DOCUMENT" #340
MP-1165 & TP-1165 EBVS BOTH IN BAD ORDER

Environmental

OMC Communications / Maintenance Plan Crude PCO

4 Crude

4 Crude Information
Flushed 8 cut→stg tk for 1 hour
FT- 095 (Grub line) FE flange needs the gasket renewed
Stm to vac jets reduced
N2→C- 1160 VTCR D/S of FCV- 69
N2→crude unit 11FI 046 was reading 157MCFD but went BP @0944 hrs 8/7/12. Reduced this rate per C1160 vacuum
Steam→east end of fan deck
Various pumps VOC vents isolated (list in coord T/O)

4 Crude Instrumentation Notes
11HCV-605 (60 PASS 5) STICKING
11TI596 READING B/O 359997
K-1100A LO LUBE ALARM 360993
E-1186-1 B/O

	Long Term Issues
--	------------------

Feed Tanks

PUMP #	Tank #	Crude Type	Gravity	FD Rate
P4700	3104	Arab	34.6/.01/.01	190
P4701	3103	ANS	33.2/0/.80	60
P4702				

☐ On ☐ Off

ATMOS. DMCIf Off, Why:

☐ On ☐ Off

VAC. DMCIf Off, Why:

☐ On ☐ Off

STAB. DMCIf Off, Why:

☐ On ☐ Off

F1100A DMCIf Off, Why:

☐ On ☐ Off

F1100B DMCIf Off, Why:

Indx	Title V	EII	Intelatrac	O/T Request	Alarm Actions		
OPS Monitor	21 Day Plan	Maximo	Trap	Corrective Action	Exapilot	Refined Orders	Find

Today Date:	8/8/2012	Name:	ca	Submit Email	<i>Report problems. Send in suggestions, improvements, changes, ideas.</i>
Shift:	Nights	Crew:	A		
<input checked="" type="radio"/> Yes <input type="radio"/> No		Are you in compliance with all CBT & Refresher Training?		Radio #	

Safety
MP-1165 SUCTION MOV CIRCUIT BOARD BYPASSED-REFER TO PSM DATABASE "BYPASS SAFETY DEVICE DOCUMENT" #340
MP-1165 & TP-1165 EBVS BOTH IN BAD ORDER

Environmental

OMC Communications / Maintenance Plan Crude PCO

4 Crude

4 Crude Information
Pressure tested 4CU relief line w/ N2 to 5 PSI G & lost 3 PSI G per hour
V- 1198→V- 3211
150 PSI G stm branch→burn zone isolated
Portable pump for atmos btms→P- 1165 suction WIP

Flushed 8 cut→stg tk for 1 hour
FT-095 (Grub line) FE flange needs the gasket renewed
Stm to vac jets reduced
N2→C-1160 VTCRD/S of FCV-69

4 Crude Instrumentation Notes
11HCV-605 (60 PASS 5) STICKING
11TI596 READING B/O 359997
K-1100A LO LUBE ALARM 360993
E-1186-1 B/O

	Long Term Issues
--	------------------

Feed Tanks

PUMP #	Tank #	Crude Type	Gravity	FD Rate
P4700				
P4701				
P4702				

☐ On ☐ Off

ATMOS. DMCIf Off, Why:

☐ On ☐ Off

VAC. DMCIf Off, Why:

☐ On ☐ Off

STAB. DMCIf Off, Why:

☐ On ☐ Off

F1100A DMCIf Off, Why:

☐ On ☐ Off

F1100B DMCIf Off, Why: